

Six Month Inspection Report **Pleasantville School District Board of Education**

Building Name/Number

Leeds Avenue School	
---------------------	--

Building Location

100 Leeds Avenue, Pleasantville, NJ 08232	
---	--

Homogeneous ID#	Material	Location	Material Cond.			Total Amt.	Damaged Amt.	Friable	Response Action/Notes
			TYP	DC	PDC				
01	12x12 Assumed Vinyl Asbestos Floor Tile - (1991 Building)	100 Wing, 200 Wing, 300 Wing, Library, Storage Closets, Custodial Closets	M	ND	PD	42,768 SF	0 SF	N	O&M
02	12x12 Assumed Vinyl Asbestos Floor Tile - (1983 Building)	400 Wing Class-rooms, Pre-K Hallway, Main Hallway, Electrical Room, Stage Storage, Teachers' Lounge	M	D	PD	5,836 SF	8 SF	N	Minor Damage: 403, Pre-K Hallway, Stage Storage O&M

*Refers to Material Type and Damage Categories

T-Material Type As:

S - Surfacing

M - Miscellaneous

T - Thermal System

DC-Damage Condition

N - No Damage

D - Damage

SD - Significant

PD-Potential Damage Categories

NPD - No Potential Damage

PD - Potential Damage

PSD - Potential Significant Damage

**Response Action

Repair

Remove

Operation & Maintenance

Encapsulate

Cathy Ladden
 Signature of Person Completing Report

Asbestos Inspector - ACC # 1122-6-004
 Title of Person Completing Report

Six Month Inspection Report Pleasantville School District Board of Education

Building Name/Number

Leeds Avenue School	
---------------------	--

Building Location

100 Leeds Avenue, Pleasantville, NJ 08232	
---	--

Homogeneous ID#	Material	Location	Material Cond.			Total Amt.	Damaged Amt.	Friable	Response Action/Notes
			TYP	DC	PDC				
03	Sheetrock/Wallboard – (1983 Building)	Multipurpose Room Foyer Exit, Teachers Lounge, Men's Bathroom, Women's Bathroom, Mechanical Room, Custodial Room, Hallway, Under Stage	M	ND	PD	1,224 SF	0 SF	N	O&M

*Refers to Material Type and Damage Categories

T-Material Type As:

S - Surfacing

M - Miscellaneous

T - Thermal System

DC-Damage Condition

N - No Damage

D - Damage

SD - Significant

PD-Potential Damage Categories

NPD - No Potential Damage

PD - Potential Damage

PSD - Potential Significant Damage

**Response Action

Repair

Remove

Operation & Maintenance

Encapsulate

Cathy Ladden
Signature of Person Completing Report

Asbestos Inspector - ACC # 1122-6-004
Title of Person Completing Report