## Six Month Inspection Report Pleasantville School District Board of Education

Leeds Avenue School	
---------------------	--

## **Building Location**

100 Leeds Avenue, Pleasantville, NJ 08232

Homogeneous	Material	Location	Material Cond.			Total Amt.	Damaged Amt.	Friable	Response Action/Notes
ID#	'		TYP	DC	PDC				
01	12x12 Assumed Vinyl Asbestos Floor Tile - (1991 Building)	100 Wing, 200 Wing, 300 Wing, Library, Storage Closets, Custodial Closets	M	ND	PD	42,768 SF	0 SF	N	O&M
02	12x12 Assumed Vinyl Asbestos Floor Tile - (1983 Building)	400 Wing Class- rooms, Pre-K Hall- way, Main Hallway, Electrical Room, Stage Storage, Teachers' Lounge	M	D	PD	5,836 SF	8 SF		Minor Damage: 403, Pre-K Hall- way, Stage Storage O&M

\*Refers to Material Type and Damage Categories

T-Material Type As:DC-Damage ConditionPD-Potential Damage Categories\*\*Response ActionS - SurfacingN - No DamageNPD - No Potential DamageRepair

M - Miscellaneous D - Damage PD - Potential Damage Remove

T - Thermal System SD - Significant PSD - Potential Significant Damage Operation & Maintenance

Encapsulate

Asbestos Inspector - ACC # 1023-6-008

Title of Person Completing Report

Signature of Person Completing Report

## **Six Month Inspection Report** Pleasantville School District Board of Education

## **Building Location**

100 Leeds Avenue, Pleasantville, NJ 08232

Homogeneous	Material	Location	Material Cond.			Total Amt.	Damaged Amt.	Friable	Response Action/Notes
ID#			TYP	DC	PDC				
03	Sheetrock/Wallboard – (1983 Building)	Multipurpose Room Foyer Exit, Teachers Lounge, Men's Bathroom, Women's Bathroom, Mechani- cal Room, Custodial Room, Hallway, Under Stage		ND	PD	1,224 SF	0 SF	N	O&M

\*Refers to Material Type and Damage Categories

DC-Damage Condition \*\*Response Action T-Material Type As: PD-Potential Damage Categories S - Surfacing N - No Damage NPD - No Potential Damage Repair

D - Damage PD - Potential Damage M - Miscellaneous Remove SD - Significant T - Thermal System

PSD - Potential Significant Damage Operation & Maintenance

Encapsulate

Asbestos Inspector - ACC # 1023-6-008

Title of Person Completing Report

Cathri Ledden Signature of Person Completing Report